



**Department of Construction & Inspections
Code Compliance Division**

700 Fifth Ave
Suite 1900
PO Box 34019
Seattle, WA 98124-4019

Phone: (206) 615-0808

TTY: (206) 233-7156

Website: seattle.gov/sdci

Office Location: 700 Fifth Avenue,
19th Floor of Seattle Municipal Tower

Complaint Location:

8717 13TH AVE NW
SEATTLE, WA 98117

Record Number: 001148-23CP

Complaint Type: Construction

Complaint Outcome: No Violation Observed

Resolution Date: Feb 02, 2023

Alleged Complaint Description: EXPOSED GAS LINESEXTENSIVE TRENCHING, UNSHORED, ETC.PSE
ALERTED.

Additional Information: As of 2/2/2023, drainage work appears to be per Side Sewer Permit 6942591-SS.
Excavations deeper than 4' have been shored. No violation of the side sewer or drainage codes enforced by
SDCI seen.

Inspections:

Type	Date	Result	Result Comments	Inspected By
Construction Investigation	2/2/2023	Completed	2/2/23 TJL: Site visit completed. No code violations seen. The utility contractor has a 3' deep trench on the south side for installation of sewer, per plan. In the front yard (east side) the contractor is excavating for an Infiltrating Drywell per plan. I did observe a 5' deep excavation near the site southeast corner and that has shoring and is secured.	Timothy Loo